


Drawing 36.

S Panel Cold PIR - fastening cold storage panels with the use of LAX fasteners, joining of cold storage panels along their length



1. S Panel Cold panel
2. LAX fastener for thermal bridge reduction (bush + EPDM seal + cap)
3. Drive screw with EPDM washer for cold storage panels fastening
4. Self-adhesive PES sealing tape
5. Drive screw with EPDM washer for flashing fastening
6. Sealant, permanently plastic
7. Polyurethane foam
8. Ob-23 flashing
9. Steel section according to the design of the structure