


Drawing 38.

S Panel Cold PIR - fastening cold storage panels in the corner



1. S Panel Cold PIR panel
2. LAX fastener for thermal bridge reduction (bush + EPDM seal + plug)
3. Drive screw with EPDM washer
4. Self-adhesive PES sealing tape
5. Sealant, permanently plastic
6. Polyurethane foam
7. Ob-15 flashing
8. Custom Ob-00 flashing (specify parameters and section drawing)
9. Steel purlin according to the design of the structure
10. Steel column according to the design of the structure